

Operating manual

pH 3310



pH meter

**Accuracy when
going to press**

The use of advanced technology and the high quality standard of our instruments are the result of a continuous development. This may result in differences between this operating manual and your meter. Also, we cannot guarantee that there are absolutely no errors in this manual. Therefore, we are sure you will understand that we cannot accept any legal claims resulting from the data, figures or descriptions.

Copyright

© Weilheim 2008, WTW GmbH

Reproduction in whole - or even in part - is prohibited without the express written permission of WTW GmbH, Weilheim.

Printed in Germany.

pH 3310 - Contents

1	Overview	5
1.1	Keypad	6
1.2	Display	7
1.3	Socket field	8
2	Safety	9
2.1	Authorized use	10
2.2	General safety instructions	10
3	Commissioning	13
3.1	Scope of delivery	13
3.2	Initial commissioning	13
3.2.1	Inserting the batteries	13
3.2.2	Switching on the meter	14
3.2.3	Setting the date and time	14
4	Operation	15
4.1	Switching on the meter	15
4.2	General operating principles	16
4.2.1	Operating modes	16
4.2.2	Navigation	17
4.2.3	Example 1 on navigation: Setting the language	19
4.2.4	Example 2 on navigation: Setting the date and time	22
4.3	Sensor-independent settings	24
4.3.1	System	24
4.3.2	Data storage	25
4.3.3	Automatic Stability control	26
4.4	pH value / ORP voltage	27
4.4.1	General information	27
4.4.2	Measuring the pH value	28
4.4.3	Measuring the ORP	30
4.4.4	Settings for pH and ORP measurements	32
4.4.5	pH calibration	34
4.4.6	Calibration interval	38
4.4.7	Carrying out an automatic calibration (AutoCal)	40
4.4.8	Carrying out a manual calibration (ConCal)	43
4.4.9	Displaying calibration records	46
4.4.10	Continuous measurement control (CMC function)	48


4.5	Storage	49
4.5.1	Manual storage	50
4.5.2	Automatic storage at intervals	51
4.5.3	Editing the measured value storage	53
4.5.4	Erasing the measurement data storage	55
4.6	Transmitting data (USB interface)	56
4.6.1	Options for data transmission	56
4.6.2	Connecting a PC	57
4.7	Reset	58
4.7.1	Resetting the measurement settings	58
4.7.2	Resetting the system settings	59
5	Maintenance, cleaning, disposal	61
5.1	Maintenance	61
5.1.1	Replacing the batteries	61
5.2	Cleaning	62
5.3	Packing	62
5.4	Disposal	62
6	What to do if	63
7	Technical data	67
7.1	General data	67
7.2	Measuring ranges, resolution, accuracy	68
8	Lists	71
	Appendix: Firmware update	75

1 Overview


The compact pH 3310 precision pH meter enables you to perform pH measurements rapidly and reliably. The pH 3310 provides the maximum degree of operating comfort, reliability and measuring certainty for all applications.

The proven calibration procedures and automatic stability control function (AR) support your work with the pH meter.

The USB interface can be used for data transmission to a PC and for software updates of the meter.



1.1 Keypad




In this operating manual, keys are indicated by brackets <..> . The key symbol (e.g. <ENTER>) generally indicates a short keystroke (under 2 sec) in this operating manual. A long keystroke (approx. 2 sec) is indicated by the underscore behind the key symbol (e.g. <ENTER>).

	<F1>:	Softkeys providing situation dependent functions, e.g.: <F1>/[Menu]: Opens the menu for measurement settings
	<F1__>:	<F1__>/[Menu]: Opens the menu for system settings
	<F2>:	
	<F2__>:	
	<On/Off>:	Switches the meter on or off
	<M>:	Selects the measured parameter
	<CAL>:	Calls up the calibration procedure
	<CAL__>:	Displays the calibration data
	<STO>:	Stores a measured value manually
	<STO__>:	Opens the menu for the automatic save function
	<RCL>:	Displays the manually stored measured values
	<RCL__>:	Displays the automatically stored measured values
	<▲>:	Increments values, scrolls
	<▼>:	Decrements values, scrolls

	<ENTER>: <ENTER__>:	Opens the menu for measurement settings / confirms entries Opens the menu for system settings
	<AR>	Freezes the measured value (HOLD function) Switches the AutoRead measurement on or off


1.2 Display



- | | |
|---|--|
| 1 | Status information |
| 2 | Measured value (with unit) |
| 3 | Measured parameter |
| 4 | Continuous measurement control (CMC function) |
| 5 | Sensor symbol (calibration evaluation, calibration interval) |
| 6 | Measured temperature (with unit) |
| 7 | Status line |
| 8 | Softkeys and date + time |

Function display indicators	AutoCal e.g. TEC	Calibration with automatic buffer recognition, e.g. with the buffer set: Technical buffers
	ConCal	Calibration with any buffers
	Error	An error occurred during calibration
	LoBat	Batteries are almost empty
	AR	Stability control (AutoRead) is active
	HOLD	Measured value is frozen (<AR> key)

1.3 Socket field



Connectors:

1	pH electrode
2	Reference electrode
3	Temperature sensor
4	USB B (device) interface
5	Service interface



Caution

Only connect sensors to the meter that cannot return any voltages or currents that are not allowed (> SELV and > current circuit with current limiting).

Almost all customary sensors fulfill these conditions.

2 Safety

This operating manual contains basic instructions that you must follow during the commissioning, operation and maintenance of the meter. Consequently, all responsible personnel must read this operating manual before working with the meter.

The operating manual must always be available within the vicinity of the meter.

Target group

The meter was developed for work in the field and in the laboratory. Thus, we assume that, as a result of their professional training and experience, the operators will know the necessary safety precautions to take when handling chemicals.

Safety instructions

Safety instructions in this operating manual are indicated by the warning symbol (triangle) in the left column. The signal word (e.g. "Caution") indicates the level of danger:



Warning

indicates instructions that must be followed precisely in order to avoid possibly great dangers to personnel.



Caution

indicates instructions that must be followed precisely in order to avoid the possibility of slight injuries or damage to the meter or the environment.

Further notes



Note

indicates notes that draw your attention to special features.



Note

indicates cross-references to other documents, e.g. operating manuals.

2.1 Authorized use

This meter is authorized exclusively for pH and ORP measurements in a laboratory or field environment.

The technical specifications as given in chapter 7 TECHNICAL DATA must be observed. Only the operation and running of the meter according to the instructions given in this operating manual is authorized.

Any other use is considered **unauthorized**.

2.2 General safety instructions

This meter is constructed and tested in compliance with the IEC 1010 safety regulations for electronic measuring instruments.

It left the factory in a safe and secure technical condition.

Function and operational safety

The smooth functioning and operational safety of the meter can only be guaranteed if the generally applicable safety measures and the specific safety instructions in this operating manual are followed during operation.

The smooth functioning and operational safety of the meter can only be guaranteed under the environmental conditions that are specified in chapter 7 TECHNICAL DATA.

If the meter was transported from a cold environment to a warm environment, the formation of condensate can lead to the faulty functioning of the meter. In this event, wait until the temperature of the meter reaches room temperature before putting the meter back into operation.

Caution

The meter is only allowed to be opened by authorized personnel.



Safe operation

If safe operation is no longer possible, the meter must be taken out of service and secured against inadvertent operation!
Safe operation is no longer possible if the meter:

- has been damaged in transport
- has been stored under adverse conditions for a lengthy period of time
- is visibly damaged
- no longer operates as described in this manual.

If you are in any doubt, please contact the supplier of the meter.

Obligations of the purchaser

The purchaser of this meter must ensure that the following laws and guidelines are observed when using dangerous substances:

- EEC directives for protective labor legislation
- National protective labor legislation
- Safety regulations
- Safety datasheets of the chemical manufacturers.

Caution

In addition to the safety instructions mentioned here, also follow the safety instructions of the sensors used.

The operating manuals of the sensors are available on the supplied CD and on the Internet under www.WTW.com.



3 Commissioning

3.1 Scope of delivery

- pH meter, pH 3310
- 4 batteries 1.5 V Mignon type AA
- Short instructions
- CD-ROM with detailed operating manual


3.2 Initial commissioning

Perform the following activities:

- Insert the supplied batteries
- Switch on the meter
- Set the date and time

3.2.1 Inserting the batteries

1	Unscrew the two screws (1) on the underside of the meter.
2	Open the battery compartment (2) on the underside of the meter.



3	Place four batteries (type Mignon AA) in the battery compartment.
---	---

**Note**

Alternatively, you can also use Ni-MH rechargeable batteries (type Mignon AA). In order to charge the batteries, an external charging device is required.

**Caution**

Make sure that the poles of the batteries are positioned correctly. The \pm signs on the batteries must correspond to the \pm signs in the battery compartment.

- 4 Close the battery compartment (2) and tighten the screws (1).

3.2.2 Switching on the meter

- 1 Press the <On/Off> key.
The meter performs a self-test.
The display shows the manufacturer's logo while the self-test is being performed.
Subsequently, the meter switches to the measuring mode (measured value display).

**Note**

The meter has an energy saving feature to avoid unnecessary battery depletion.

The energy saving feature switches off the meter if no key is pressed during the adjusted interval. (How to set the switch-off interval, see section 4.3.1).

3.2.3 Setting the date and time

- 1 See section 4.2.4

4 Operation

4.1 Switching on the meter


Switching on

Press the <On/Off> key.

The meter performs a self-test.

The display shows the manufacturer's logo while the self-test is being performed.

The measured value display appears.



Switching off

Press the <On/Off> key.

Automatic switch-off

The instrument has an automatic switch-off function in order to save the batteries (see section 4.3.1). The automatic switch-off switches off the meter if no key is pressed for an adjustable period.

The automatic switch-off is not active

- if the communication cable is connected
- if the *Autom. saving* function is active, or with automatic data transmission

Display illumination

The meter automatically switches off the display illumination if no key has been pressed for 15 seconds. The illumination is switched on with the next keystroke again.

You can also generally switch the display illumination on or off (see section 4.3.1).

4.2 General operating principles

This section contains basic information on the operation of the pH 3310.

Operating elements, display

An overview of the operating elements and the display is given in section 1.1 and section 1.2.

Operating modes, navigation

An overview of the operating modes and navigation of the pH 3310 is given in section 4.2.1 and section 4.2.2.

4.2.1 Operating modes

The meter has the following operating modes:

- Measurement

The measurement data of the connected sensor is shown in the measured value display

- Calibration

The course of a calibration with calibration information, functions and settings is displayed

- Storage in memory

The meter stores measuring data manually or automatically

- Transmitting data

The meter transmits measuring data and calibration records to the USB interface automatically or manually.

- Setting

The system menu or a sensor menu with submenus, settings and functions is displayed

4.2.2 Navigation

Measured value display

In the measured value display, you can

- open the menu for calibration and measurement settings with **<F1>** (short keystroke).
- open the *Storage & config* menu with the sensor-independent settings by pressing **<F1__>** (long keystroke, approx. 2 s on **<F1>**).
- change the display in the selected measuring window (e. g. pH <-> mV) by pressing **<M>**.


Menus and dialogs

The menus for settings and dialogs in procedures contain further submenus. The selection is made with the **<▲><▼>** keys. The current selection is displayed with a frame.

- Submenus

The name of the submenu is displayed at the upper edge of the frame. Submenus are opened by confirming with **<ENTER>**.


Example:



- Settings

Settings are indicated by a colon. The current setting is displayed on the right-hand side. The setting mode is opened with **<ENTER>**.

Subsequently, the setting can be changed with **<▲><▼>** and **<ENTER>**. Example:



- **Functions**

Functions are designated by the name of the function. They are immediately carried out by confirming with <ENTER>.

Example: Display the *Calibration record* function.

pH

Calibration record	
Data storage	
Buffer:	TEC
One point calibration:	Yes
Calibration interval:	7 d
Unit for slope:	mV/pH

Back 22.11.2010
 08:00

Messages

Information is marked by the **i** symbol. It cannot be selected.

Example:

pH

Calibration record	
Data storage	
Buffer:	TEC
One point calibration:	Yes
Calibration interval:	7 d
Unit for slope:	mV/pH

i 2.00 4.01 7.00 10.01

Back 22.11.2010
 08:00

Note


The principles of navigation are explained in the two following sections by reference of examples:

- Setting the language (section 4.2.3)
- Setting the date and time (see section 4.2.4).




4.2.3 Example 1 on navigation: Setting the language


- 1 Press the <On/Off> key.
The measured value display appears.
The instrument is in the measuring mode.




- 2 Using <F1__>/[Menu] open the *Storage & config* menu.
The instrument is in the setting mode.




- 3 Select the *System* submenu with <▲><▼>. The current selection is displayed with a frame.
- 4 Open the *System* submenu with <ENTER>.



- 5 Select the *General* submenu with <**▲**><**▼**>. The current selection is displayed with a frame.
- 6 Open the *General* submenu with <**ENTER**>.



- 7 Open the setting mode for the *Language* with <**ENTER**>.



- 8 Select the required language with <**▲**><**▼**>.

- 9 | Confirm the setting with <ENTER>. The meter switches to the measuring mode. The selected language is active.

4.2.4 Example 2 on navigation: Setting the date and time

The meter has a clock with a date function. The date and time are indicated in the status line of the measured value display.

When storing measured values and calibrating, the current date and time are automatically stored as well.

The correct setting of the date and time and date format is important for the following functions and displays:

- Current date and time
- Calibration date
- Identification of stored measured values.

Therefore, check the time at regular intervals.



Note

After a fall of the supply voltage (empty batteries), the date and time are reset to 01.01.2008 00, 00:00 hours.

Setting the date, time and date format

The date format can be switched from the display of day, month, year (*dd.mm.yyyy*) to the display of month, day, year (*mm/dd/yyyy* or *mm.dd.yyyy*).

- | | |
|---|--|
| 1 | In the measured value display:
Using < F1 >/[Menu], open the <i>Storage & config</i> menu.
The instrument is in the setting operating mode. |
| 2 | Select and confirm the <i>System / Clock</i> menu with < ▲ >< ▼ > and < ENTER >.
The setting menu for the date and time opens up. |
| 3 | Select and confirm the <i>Time</i> menu with < ▲ >< ▼ > and < ENTER >.
The hours are highlighted. |

Clock

Date format:	dd.mm.yyyy
Date:	30.10.2008
Time:	14:53:40

Back 22.11.2010
 08:00

4	Change and confirm the setting with < ▲ >< ▼ > and < ENTER >. The minutes are highlighted.
5	Change and confirm the setting with < ▲ >< ▼ > and < ENTER >. The seconds are highlighted.
6	Change and confirm the setting with < ▲ >< ▼ > and < ENTER >. The time is set.
7	If necessary, set the <i>Date</i> and <i>Date format</i> . The setting is made similarly to that of the time.
8	If necessary, select and set the <i>Date</i> with < ▲ >< ▼ > and < ENTER >.
9	To make further settings, switch to the next higher menu level with < F1 >/[Back]. or Switch to the measured value display with < M >. The instrument is in the measuring mode.

4.3 Sensor-independent settings

The *Storage & config* menu comprises the following settings:

- *System* (see section 4.3.1).
- *Data storage* (see section 4.3.1)

4.3.1 System

Overview

The following sensor-independent meter characteristics can be adjusted in the *Storage & config/System* menu:

- Menu language
- Beep on keystroke
- Illumination
- Display contrast
- Interval of the automatic switch-off
- Data interface
- Clock and date function
- Reset of all sensor-independent system settings to the default condition

Settings

To open the *Storage & config* menu, press the **<F1>**/[Menu] or **<ENTER>**key in the measured value display. After completing the settings, switch to the measured value display with **<M>**.

Menu item	Setting	Description
<i>System / General / Language</i>	<i>Deutsch</i> <i>English</i> (further)	Select the menu language
<i>System / General / Beep</i>	<i>On</i> <i>Off</i>	Switch on/off the beep on keystroke
<i>System / General / Illumination</i>	<i>Auto</i> <i>On</i> <i>Off</i>	Switching the display illumination on/off
<i>System / General / Contrast</i>	0 ... 100 %	Changing the display contrast
<i>System / General / Switchoff time</i>	10 min ... 24 h	Adjust the switch-off time
<i>System / Interface / Baud rate</i>	1200, 2400, 4800, 9600, 19200	Baud rate of the data interface

Menu item	Setting	Description
<i>System / Interface / Output format</i>	<i>ASCII / CSV</i>	Output format for data transmission For details, see section 4.6
<i>System / Interface / Decimal separator</i>	<i>Dot (xx.x) Comma (xx,x)</i>	Decimal separator
<i>System / Interface / Output header</i>		Output of a header for <i>Output format: CSV</i>
<i>System / Clock</i>	<i>Time Date Date format</i>	Settings of time and date. For details, see section 4.2.4
<i>System / Service information</i>		Hardware version and software version of the meter are displayed.
<i>System / Reset</i>	-	Resets the system settings to the default values. For details, see section 4.7.2

4.3.2 Data storage

This menu contains all functions to display, edit and erase stored measured values and calibration records.

Note

Detailed information on the storage functions of the pH 3310 is given in section 4.5.



4.3.3 Automatic *Stability control*

The automatic *Stability control* function continuously checks the stability of the measurement signal. The stability has a considerable impact on the reproducibility of measured values.

You can activate or switch off the automatic *Stability control* function (see section 4.3.1).

The measured parameter flashes on the display

- as soon as the measured value is outside the allowed stability range
- if you switch over between the measured parameters with <M>.
- if the automatic *Stability control* function is switched off.

4.4 pH value / ORP voltage

4.4.1 General information

You can measure the following variables:

- pH value []
- ORP [mV]



Temperature measurement

Warning

When a grounded PC is connected, measurements cannot be performed in grounded media as incorrect values would result. The USB-A (Device) is not galvanically isolated.

For reproducible pH measurements, it is essential to measure the temperature of the test sample.

You have the following possibilities to measure the temperature:

- Automatic measurement of the temperature by the temperature sensor (NTC30 or Pt1000) integrated in electrode.
- Manual determination and input of the temperature.

The meter recognizes whether a suitable sensor is connected and automatically switches on the temperature measurement.

The display of the temperature indicates the active temperature measuring mode:

Temperature sensor	Resolution of the temp. display	Mode
yes	0.1 °C	Automatic with temperature sensor
-	1 °C	Manual


Preparatory activities

Perform the following preparatory activities when you want to measure:

- | | |
|---|--|
| 1 | Connect a pH or ORP electrode to the meter.
The pH measuring window is displayed. |
| 2 | If necessary, select the pH or mV display with <M>. |
| 3 | Adjust the temperature of the solutions and measure the current temperature if the measurement is made without a temperature sensor. |
| 4 | Calibrate or check the meter with the combination electrode. |

4.4.2 Measuring the pH value

- | | |
|---|--|
| 1 | Perform the preparatory activities according to section 4.4.1. |
| 2 | Immerse the pH electrode in the test sample. |



- | | |
|---|---------------------------------------|
| 3 | Select the pH or mV display with <M>. |
|---|---------------------------------------|

Stability control (AutoRead)

The stability control function (AutoRead) continually checks the stability of the measurement signal. The stability has a considerable impact on the reproducibility of measured values.

The measured parameter flashes on the display

- as soon as the measured value is outside the stability range
- when the automatic *Stability control* is switched off.

You can start the *Stability control* manually at any time, irrespective of the setting for automatic *Stability control* (see page 26) in the *System* menu.

- | | |
|---|---|
| 1 | Freeze the measured value with <AR>. The [HOLD] status indicator is displayed. The HOLD function is active. |
| 2 | Using <ENTER>, activate the <i>Stability control</i> function manually. The [AR] status indicator appears while the measured value is assessed as not stable. A progress bar is displayed and the display of the measured parameter flashes. The [HOLD][AR] status indicator appears as soon as a stable measured value is recognized. The current measurement data are output to the interface. Measurement data meeting the stability control criterion are marked by AR. |



Note

You can prematurely terminate the *Stability control* function manually

with <ENTER> at any time. If the *Stability control* function is prematurely terminated, the current measurement data are output to the interface without AutoRead info.

- 3 Using <ENTER>, start a further measurement with stability control.
or
Release the frozen measured value again with <AR> or <M>. The [AR] status display disappears. The display switches back to the previous representation.

Criteria for a stable measured value

The *Stability control* function checks whether the measured values are stable within the monitored time interval.

Measured parameter	Time interval	Stability in the time interval
pH value	15 seconds	ΔpH : better than 0.01
Temperature	15 seconds	$\Delta T (\text{ }^\circ \text{C})$: Better than 0.02


The minimum duration until a measured value is assessed as stable is the monitored time interval. The actual duration is mostly longer.

4.4.3 Measuring the ORP

**Note**

ORP electrodes are not calibrated. However, you can check ORP electrodes using a test solution.

- 1 Perform the preparatory activities according to section 4.4.1.
- 2 Submerge the ORP electrode in the sample.



- 3 Select the mV display with <M>.

**Stability control
(AutoRead)**

The stability control function (AutoRead) continually checks the stability of the measurement signal. The stability has a considerable impact on the reproducibility of measured values.

The measured parameter flashes on the display

- as soon as the measured value is outside the stability range
- when the automatic *Stability control* is switched off.

You can start the *Stability control* manually at any time, irrespective of the setting for automatic *Stability control* (see page 26) in the *System* menu.

- 1 Freeze the measured value with <AR>. The [HOLD] status indicator is displayed. The HOLD function is active.

- 2 Using <ENTER>, activate the *Stability control* function manually.

The [AR] status indicator appears while the measured value is assessed as not stable. A progress bar is displayed and the display of the measured parameter flashes.

The [HOLD][AR] status indicator appears as soon as a stable measured value is recognized. The current measurement data are output to the interface.

Measurement data meeting the stability control criterion are marked by AR.

Note



You can prematurely terminate the *Stability control* function manually with <ENTER> at any time. If the *Stability control* function is prematurely terminated, the current measurement data are output to the interface without AutoRead info.

- 3 Using <ENTER>, start a further measurement with stability control.

or

Release the frozen measured value again with <AR> or <M>. The [AR] status display disappears. The display switches back to the previous representation.

Criteria for a stable measured value

The *Stability control* function checks whether the measured values are stable within the monitored time interval.

Measured parameter	Time interval	Stability in the time interval
ORP	15 seconds	Δ mV: better than 0.3
Temperature	15 seconds	Δ T ($^{\circ}$ C): Better than 0.02

The minimum duration until a measured value is assessed as stable is the monitored time interval. The actual duration is mostly longer.

4.4.4 Settings for pH and ORP measurements

Overview	The following settings are possible for pH and ORP measurements:																						
	<ul style="list-style-type: none"> ● Resolution ● <i>Calibration interval</i> ● Buffers for calibration ● Unit of the temperature ● Automatic stability control ● <i>Unit for slope</i> ● <i>Calibration record</i> (display) 																						
Settings	<p>The settings are made in the measuring menu of the pH/ORP measurement. To open the settings, activate the relevant measuring window in the measured value display and press the <ENTER> key <u>shortly</u>. After completing the settings, switch to the measured value display with <M>.</p>																						
	<table border="1"> <thead> <tr> <th>Menu item</th> <th>Possible setting</th> <th>Description</th> </tr> </thead> <tbody> <tr> <td><i>Calibration / Calibration record</i></td> <td>-</td> <td>Displays the calibration record of the last calibration.</td> </tr> <tr> <td><i>Calibration /Buffer</i></td> <td>TEC NIST/DIN ConCal ...</td> <td>Buffer sets to be used for pH calibration. More buffers and details, see section 4.4.5.</td> </tr> <tr> <td><i>Calibration /One point calibration</i></td> <td>Yes No</td> <td>Rapid calibration with 1 buffer</td> </tr> <tr> <td><i>Calibration / Calibration interval</i></td> <td>1 ... 999 d</td> <td><i>Calibration interval</i> for the pH electrode (in days). The meter reminds you to calibrate regularly by the flashing sensor symbol in the measuring window.</td> </tr> <tr> <td><i>Calibration /Unit for slope</i></td> <td>mV/pH %</td> <td>Unit of the slope. The % display refers to the Nernst slope of -59.16 mV/pH (100 x determined slope/Nernst slope).</td> </tr> <tr> <td><i>Man. temperature</i></td> <td>-25 ... +130 °C</td> <td>Entry of the manually determined temperature. For measurements without temperature sensor only.</td> </tr> </tbody> </table>		Menu item	Possible setting	Description	<i>Calibration / Calibration record</i>	-	Displays the calibration record of the last calibration.	<i>Calibration /Buffer</i>	TEC NIST/DIN ConCal ...	Buffer sets to be used for pH calibration. More buffers and details, see section 4.4.5.	<i>Calibration /One point calibration</i>	Yes No	Rapid calibration with 1 buffer	<i>Calibration / Calibration interval</i>	1 ... 999 d	<i>Calibration interval</i> for the pH electrode (in days). The meter reminds you to calibrate regularly by the flashing sensor symbol in the measuring window.	<i>Calibration /Unit for slope</i>	mV/pH %	Unit of the slope. The % display refers to the Nernst slope of -59.16 mV/pH (100 x determined slope/Nernst slope).	<i>Man. temperature</i>	-25 ... +130 °C	Entry of the manually determined temperature. For measurements without temperature sensor only.
Menu item	Possible setting	Description																					
<i>Calibration / Calibration record</i>	-	Displays the calibration record of the last calibration.																					
<i>Calibration /Buffer</i>	TEC NIST/DIN ConCal ...	Buffer sets to be used for pH calibration. More buffers and details, see section 4.4.5.																					
<i>Calibration /One point calibration</i>	Yes No	Rapid calibration with 1 buffer																					
<i>Calibration / Calibration interval</i>	1 ... 999 d	<i>Calibration interval</i> for the pH electrode (in days). The meter reminds you to calibrate regularly by the flashing sensor symbol in the measuring window.																					
<i>Calibration /Unit for slope</i>	mV/pH %	Unit of the slope. The % display refers to the Nernst slope of -59.16 mV/pH (100 x determined slope/Nernst slope).																					
<i>Man. temperature</i>	-25 ... +130 °C	Entry of the manually determined temperature. For measurements without temperature sensor only.																					

Menu item	Possible setting	Description
<i>Temperature unit</i>	°C °F	Temperature unit, degrees Celsius or degrees Fahrenheit. All temperatures are displayed with the selected unit.
<i>Resolution pH</i>	0.001 0.01 0.1	Resolution of the pH display:
<i>Resolution mV</i>	0.1 1	Resolution of the mV display:
<i>Stability control</i>	On / Off	Switches on or off the automatic stability control during measurement (see section 4.3.3)
<i>Reset</i>	-	Resets all sensor settings to the delivery condition (see section 4.7.1).

4.4.5 pH calibration

Why calibrate?

pH combination electrodes age. This changes the zero point (asymmetry) and slope of the pH combination electrode. As a result, an inexact measured value is displayed. Calibration determines and stores the current values of the zero point and slope of the electrode. Thus, you should calibrate at regular intervals.

When do you have to calibrate?

- After connecting another combination electrode
- When the calibration interval has expired

Buffer sets for calibration

You can use the buffer sets quoted in the table for an automatic calibration. The pH values are valid for the specified temperature values. The temperature dependence of the pH values is taken into consideration during the calibration.

No.	Buffer set*	pH values	at
1	<i>ConCal</i>	Any	Any
2	<i>NIST/DIN</i> DIN buffers according to DIN 19266 and NIST Traceable Buffers	1,679 4,006 6,865 9,180 12,454	25 °C
3	<i>TEC</i> WTW Technical buffers	2,000 4,010 7,000 10,011	25 °C
4	<i>Merck 1</i> *	4,000 7,000 9,000	20 °C
5	<i>Merck 2</i> *	1,000 6,000 8,000 13,000	20 °C
6	<i>Merck 3</i> *	4,660 6,880 9,220	20 °C
7	<i>Merck 4</i> *	2,000 4,000 7,000 10,000	20 °C
8	<i>Merck 5</i> *	4,010 7,000 10,000	25 °C

No.	Buffer set*	pH values	at
9	DIN 19267	1,090 4,650 6,790 9,230	25 °C
10	Mettler Toledo USA *	1,679 4,003 7,002 10,013	25 °C
11	Mettler Toledo EU *	1,995 4,005 7,002 9,208	25 °C
12	Fisher *	2,007 4,002 7,004 10,002	25 °C
13	Fluka BS *	4,006 6,984 8,957	25 °C
14	Radiometer *	1,678 4,005 7,000 9,180	25 °C
15	Baker *	4,006 6,991 10,008	25 °C
16	Metrohm *	3,996 7,003 8,999	25 °C
17	Beckman *	4,005 7,005 10,013	25 °C
18	Hamilton Duracal *	4,005 7,002 10,013	25 °C
19	Precisa *	3,996 7,003 8,999	25 °C

No.	Buffer set*	pH values	at
20	<i>Reagecon TEC</i> *	2,000 4,010 7,000 10,000	25 °C
21	<i>Reagecon 20</i> *	2,000 4,000 7,000 10,000 13,000	20 °C
22	<i>Reagecon 25</i> *	2,000 4,000 7,000 10,000 13,000	25 °C
23	<i>Chemsolute</i> *	4,000 7,000 10,000	20 °C
24	<i>USABlueBook</i> *	4,000 7,000 10,000	20 °C

* Brand names or trade names are trademarks of their respective owners protected by law.



Note

The buffers are selected in the menu, pH / <F1>/[Menu] / Calibration / Buffer (see page 32).

Calibration points

Calibration can be performed using one to five buffer solutions in any order (single-point to five-point calibration). The meter determines the following values and calculates the calibration line as follows:

	Determined values	Displayed calibration data
1-point	Asy	<ul style="list-style-type: none"> ● Zero point = Asy ● Slope = Nernst slope (-59.16 mV/pH at 25 °C)
2-point	Asy Slp.	<ul style="list-style-type: none"> ● Zero point = Asy ● Slope = Slp.

	Determined values	Displayed calibration data
3-point to 5-point	Asy S/p.	<ul style="list-style-type: none"> ● Zero point = Asy ● Slope = S/p. <p>The calibration line is calculated by linear regression.</p>



Stability control

Note

You can display the slope in the units, mV/pH or % (see page 24).

The calibration procedure automatically activates the stability control function. The current measurement with stability control can be terminated at any time (accepting the current value).

Calibration record

The new calibration values are displayed when the calibration is finished.

Display calibration and output to interface



You can have the data of the last calibration displayed (see page 56). Subsequently, you can transmit the displayed calibration data to the interface, e. g. a PC, with the **<F2>/[USB output]** key.

Note

The calibration record is automatically transmitted to the interface after calibrating.

Sample record

```

31.10.2008 16:55
pH 3310
Ser. no. 08502113

CALIBRATION pH

AutoCal TEC
Buffer 1          4.01
Buffer 2          7.00
Buffer 3          10.01
Voltage 1         184.0 mV    24.0 °C
Voltage 2         3.0 mV      24.0 °C
Voltage 3         -177.0 mV   24.0 °C
Slope             -60.2 mV/pH
Asymmetry        4.0 mV
Sensor            +++
etc...

```

Calibration evaluation

After calibrating, the meter automatically evaluates the calibration. The zero point and slope are evaluated separately. The worse evaluation of both is taken into account. The evaluation appears on the display and in the calibration record.

Display	Calibration record	Zero point [mV]	Slope [mV/pH]
	+++	-15 ... +15	-60.5 ... -58
	++	-20 ... +20	-58 ... -57
	+	-25 ... +25	-61 ... -60.5 or -57 ... -56
	-	-30 ... +30	-62 ... -61 or -56 ... -50
Clean the combination electrode according to the electrode operating manual			
Error	Error	< -30 or > 30	... -62 or ... -50
Eliminate the error according to chapter 6 WHAT TO DO IF... (page 63)			

Preparatory activities

Perform the following preparatory activities when you want to calibrate:

- 1 Connect the pH combination electrode to the meter.
The pH measuring window is displayed.
- 2 Keep the buffer solutions ready. Adjust the temperature of the buffer solutions, or measure the current temperature, if you measure without a temperature sensor.

4.4.6 Calibration interval

The calibration evaluation is indicated on the display as a sensor symbol.

The sensor symbol flashes after the adjusted calibration interval has expired. It is still possible to measure.

Note

To ensure the high measuring accuracy of the measuring system, calibrate after the calibration interval has expired.

Setting the calibration interval

The calibration interval is set to 7 days (d7) in the factory.
You can change the interval (1 ... 999 days):

- | | |
|---|--|
| 1 | Open the menu for measurement settings with < F1 >/[Menu]. |
| 2 | In the <i>Calibration / Calibration interval</i> menu, set the calibration interval with < ▲ >< ▼ >. |
| 3 | Confirm the setting with < ENTER >. |
| 4 | Exit the menu with < M >. |

4.4.7 Carrying out an automatic calibration (AutoCal)

Make sure that in the sensor menu, *Buffer* menu, the buffer set is correctly selected (see page 32).

Use any one to five buffer solutions of the selected buffer set in ascending or descending order.


Below, calibration with Technical buffers (TEC) is described. When other buffer sets are used, other nominal buffer values are displayed. Apart from that, the procedure is identical.

Note




If single-point calibration was set in the menu, the calibration procedure is automatically finished with the measurement of buffer solution 1 and the calibration record is displayed.

- | | |
|---|---|
| 1 | In the measured value display, select the measured parameter, pH or mV with <M>. |
| 2 | Start the calibration with <CAL>. The calibration display for the first buffer appears (voltage display). |



- | | |
|---|--|
| 3 | Thoroughly rinse the electrode with deionized water. |
| 4 | Immerse the electrode in buffer solution 1. |
| 5 | When measuring without temperature sensor:
Measure the temperature of the buffer manually and enter it with <▲><▼>. |
| 6 | Start the measurement with <ENTER>. The measured value is checked for stability (stability control). The [AR] status indicator is displayed. The measured parameter flashes. |



- | | |
|---|---|
| 7 | Wait for the end of the measurement with stability control or accept the calibration value with <ENTER>. The calibration display for the next buffer appears. |
| 8 | If necessary, terminate the calibration as a single-point calibration with <M>. The calibration record is displayed. |




Note

For **single-point calibration**, the instrument uses the Nernst slope (-59.16 mV/pH at 25 °C) and determines the zero point of the electrode.

Continuing with two-point calibration


- | | |
|----|--|
| 9 | Thoroughly rinse the electrode with deionized water. |
| 10 | Immerse the electrode in buffer solution 2. |
| 11 | When measuring without temperature sensor:
Measure the temperature of the buffer manually and enter it with <▲><▼>. |
| 12 | Start the measurement with <ENTER>. The measured value is checked for stability (stability control). The [AR] status indicator is displayed. The measured parameter flashes. |



- | | |
|----|---|
| 13 | Wait for the measurement with stability control to be completed or terminate the stability control and take over the calibration value with <ENTER>. The calibration display for the next buffer appears. |
| 14 | If necessary, terminate the calibration as a two-point calibration with <M>. The calibration record is displayed. |

**Continuing with three-
to five-point calibration**

- | | |
|----|--|
| 15 | Thoroughly rinse the combination electrode with deionized water. |
| 16 | Immerse the electrode in buffer solution 3. |
| 17 | When measuring without temperature sensor:
Measure the temperature of the buffer manually and enter it with <▲><▼>. |
| 18 | Start the measurement with <ENTER>. The measured value is checked for stability (stability control). The [AR] status indicator is displayed. The measured parameter flashes. |



- | | |
|----|---|
| 19 | Wait for the measurement with stability control to be completed or terminate the stability control and take over the calibration value with <ENTER>. The calibration display for the next buffer appears (voltage display). |
| 20 | If necessary, use <M> to finish the calibration.
The calibration record is displayed.
or
Switch to calibration with the next buffer with <ENTER>. |

Note



Calibration is automatically completed after the last buffer of a buffer set has been measured. Then the calibration record is displayed.

The calibration line is determined by linear regression.

4.4.8 Carrying out a manual calibration (ConCal)

Make sure that in the sensor menu, *Buffer* menu, the *ConCal*/buffer set is correctly selected (see page 32).


Use any one to five buffer solutions in ascending or descending order.

**Note**


If single-point calibration was set in the menu, the calibration procedure is automatically finished with the measurement of buffer solution 1 and the calibration record is displayed.

- | | |
|---|---|
| 1 | In the measured value display, select the measured parameter pH or mV with <M>. |
|---|---|


- | | |
|---|--|
| 2 | Start the calibration with <CAL>. The calibration display appears. |
|---|--|



- | | |
|---|--|
| 3 | Thoroughly rinse the combination electrode with deionized water. |
| 4 | Immerse the electrode in buffer solution 1. |
| 5 | When measuring without temperature sensor:
Measure the temperature of the buffer manually and enter it with <▲><▼>. |
| 6 | Start the measurement with <ENTER>. The measured value is checked for stability (stability control). The [AR] status indicator is displayed. The measured parameter flashes. |



- 7 Wait for the measurement with stability control to be completed.
Set the nominal buffer value for the measured temperature with <▲><▼>.



- 8 Set the nominal buffer value for the measured temperature with <▲><▼>.
- 9 Accept the calibration value with <ENTER>. The calibration display for the next buffer appears (voltage display).
- 10 If necessary, terminate the calibration as a single-point calibration with <M>. The calibration record is displayed.


Note



For **single-point calibration**, the instrument uses the Nernst slope (-59.16 mV/pH at 25 °C) and determines the zero point of the electrode.

Continuing with two-point calibration

11	Thoroughly rinse the combination electrode with deionized water.
12	Immerse the electrode in buffer solution 2.
13	When measuring without temperature sensor: Measure the temperature of the buffer manually and enter it with <▲><▼>.
14	Start the measurement with <ENTER>. The measured value is checked for stability (stability control). The [AR] status indicator is displayed. The measured parameter flashes.
15	Wait for the measurement with stability control to be completed or terminate the stability control and take over the calibration value with <ENTER>. The pH value of the buffer solution is displayed.




16	Set the nominal buffer value for the measured temperature with <▲><▼>.
17	Accept the calibration value with <ENTER>. The calibration display for the next buffer appears (voltage display).
18	If necessary, finish the calibration procedure as a two-point calibration with <M>. The calibration record is displayed.

Continuing with three-to five-point calibration

19	Thoroughly rinse the electrode with deionized water.
20	Immerse the electrode in the next buffer solution.
21	When measuring without temperature sensor: Measure the temperature of the buffer manually and enter it with <▲><▼>.

- | | |
|----|---|
| 22 | Start the measurement with < ENTER >. The measured value is checked for stability (stability control). The [AR] status indicator is displayed. The measured parameter flashes. |
| 23 | Wait for the measurement with stability control to be completed or terminate the stability control and take over the calibration value with < ENTER >. The pH value of the buffer solution is displayed. |



- | | |
|----|---|
| 24 | Set the nominal buffer value for the measured temperature with < ▲><▼> . |
| 25 | Accept the calibration value with < ENTER >. The calibration display for the next buffer appears (voltage display). |
| 26 | If necessary, use < M > to finish the calibration. The calibration record is displayed.
or
Continue calibrating using the next buffer with < ENTER >. |

Note



After the fifth buffer has been measured the calibration is automatically finished. Then the calibration record is displayed. The calibration line is determined by linear regression.

4.4.9 Displaying calibration records

The calibration data can be displayed and then output to the interface.

The calibration record of the last calibration is to be found under the menu item, *Calibration / Calibration record*. To open it in the measured value display, press the <**CAL**> key.

The calibration records of the last calibrations (up to 10) are available in the menu, <**F1**>/[Menu] / *Calibration / Calibration data storage* and in the menu, <**F1**>/[Menu] / *Storage & config/Data storage / Calibration data storage*.

Displaying the calibration record

Menu item	Setting/ function	Description
<i>Calibration / Calibration data storage /Display</i> or <i>Data storage / Calibration data storage /Display</i>	-	<p>Displays the calibration record.</p> <p>Further options:</p> <ul style="list-style-type: none"> ● Scroll through the calibration records with <▲><▼>. ● Output the displayed calibration record to the interface with <F2>/[USB output]. ● Quit the display with <F1>/[Back] or <ENTER>. ● Switch directly to the measured value display with <M>.
<i>Calibration / Calibration data storage / Output to USB</i> or <i>Data storage / Calibration data storage /Output to USB</i>	-	Outputs the calibration records to the interface.

Sample

```

31.10.2008 16:55
pH 3310
Ser. no. 08502113

CALIBRATION pH

AutoCal TEC
Buffer 1           4.01
Buffer 2           7.00
Buffer 3           10.01
Voltage 1          184.0 mV    24.0 °C
Voltage 2          3.0 mV      24.0 °C
Voltage 3          -177.0 mV   24.0 °C
Slope              -60.2 mV/pH
Asymmetry          4.0 mV
Sensor             +++
etc...


```

4.4.10 Continuous measurement control (CMC function)

The continuous measurement control (CMC function) enables to quickly and safely evaluate the current measured value at a glance.

After each successful calibration, the scale of the pH measuring range is displayed in the measured value display. Here you can very easily see whether or not the current measured value is in the calibrated part of the measuring range.

The following information is displayed:



- | | |
|---|--|
| 1 | Measuring range for which a valid calibration is available (white). Measured values in this range are suitable for documentation. |
| 2 | Measuring range for which no valid calibration is available (shaded). Measured values in this range are not suitable for documentation. If necessary, calibrate the meter with buffers covering this measuring range.
If the current measured value is outside the calibrated range, this area is shaded stronger.
If a measured value is outside the measuring range pH 0 - 14, overflow arrows are displayed at the left or right edge of the measuring range. |
| 3 | Current measured pH value (pointer) |
| 4 | Line marks for all nominal buffer values used for the last valid calibration |

The limits of the calibrated range are determined by the buffers used for calibration:

Lower limit:	Buffer with the lowest pH value minus 2 pH units
Upper limit:	Buffer with the highest pH value plus 2 pH units

4.5 Storage

You can transmit measured values (datasets) to the data storage:

- Manual storage (see section 4.5.1)
- Automatic storage at intervals (see section 4.5.2)

Each storage process transmits the current dataset to the interface at the same time.

Measurement dataset

A complete dataset consists of:

- Date/time
- Measured value of the connected sensor
- Measured temperature value of the connected sensor
- AutoRead info: *AR* appears with the measured value if the AutoRead criterion was met while storing (stable measured value). Otherwise, the *AR* display is missing.
- Calibration evaluation: +++, ++, +, -, or no evaluation

Storage locations


The pH 3310 meter has two measurement data memories. The measured values recorded either manually or automatic are stored separately in individual measurement data memories.

Storage	Maximum number of datasets
<i>Manual data storage</i>	200
<i>Automatic data storage</i>	5000

4.5.1 Manual storage

You can transmit a measurement dataset to the data storage as follows: The dataset is at the same time output to the interface:


- 1 | Press the **<STO>** key shortly.
The menu for manual storage appears.



- 2 | If necessary, change and confirm the ID number (1 ... 10000) with **<▲><▼>** and **<ENTER>**.
The dataset is stored. The instrument switches to the measured value display.

If the storage is full

The following window appears if all 200 storage locations are occupied:




You have the following options:

- To erase the entire storage, confirm Yes.
- To cancel the storage process and switch to the measured value display, confirm No. Then you can e.g. transmit the stored data to a PC (see section 4.5.3) and subsequently erase the storage (see section 4.5.4).

4.5.2 Automatic storage at intervals

The storage interval (*Interval*) determines the chronological interval between automatic storage processes. Each storage process transmits the current dataset to the interface at the same time.

Configuring the automatic storage function



Settings


You can configure the automatic storage function with the following settings:

Menu item	Possible setting	Description
ID number	1 ... 10000	ID number for the dataset series.
Interval	1 s, 5 s, 10 s, 30 s, 1 min, 5 min, 10 min, 15 min, 30 min, 60 min	Storage interval. The lower limit of the storage interval can be restricted by the number of free storage locations. The upper limit is restricted by the storage duration.

Menu item	Possible setting	Description
<i>Duration</i>	1 min ... x min	<p>Storage duration. Specifies after which time the automatic storage should be terminated.</p> <p>The lower limit of the storage duration is restricted by the storage interval. The upper limit is restricted by the number of free storage locations.</p>

Starting the automatic storage function

To start the automatic storage function, select *Continue* with <▲><▼> and confirm with <ENTER>. The meter switches to the measured value display.



The active automatic storage function can be recognized from the progress bar in the status line. The progress bar shows the remaining storage duration.



Note

If the automatic storage function is activated, only the following keys are active: Softkeys, <M>, <STO_> and <On/Off>. The other keys and the automatic switch-off function are deactivated.


Energy saving mode ([Eco mode])

If the automatic storing function is active, the meter provides an energy saving mode ([Eco mode]) to avoid unnecessary energy consumption. The energy saving mode switches off functions of the meter that are not required for the automatic storage of measurement data (such as the display). By pressing any key the energy saving mode is switched off again.

Terminating the automatic storage function prematurely

Proceed as follows to switch off the automatic storage function before the adjusted storage duration has expired:

- 1 Press the **<STO_>** key.
The following window appears.



- 2 Using **<▲><▼>**, select Yes and confirm with **<ENTER>**.
The meter switches to the measured value display.
The automatic storage function is terminated.

4.5.3 Editing the measured value storage

The contents of the manual or automatic measurement data storage can be shown on the display and output to the interface.

Each of the measurement data memories has a function to erase the entire contents.

Editing the data storage


The storage is edited in the menu, *Storage & config/ Data storage*. To open the *Storage & config* menu, press the **<F1_>/[Menu]** key in the measured value display.

**Note**

The settings are explained here using the manual storage as an example. The same settings and functions are available for the automatic storage.

Settings	Menu item	Setting/ function	Description
	<i>Data storage / Manual data storage / Display</i>	-	<p>Displays all measurement datasets page by page.</p> <p>Further options:</p> <ul style="list-style-type: none"> ● Scroll through the datasets with <▲>/<▼>. ● Output the displayed dataset to the interface with <F2>/[USB output]. ● Quit the display with <F1>/[Back].
	<i>Data storage / Manual data storage / Erase</i>	-	<p>Erases the entire manual measurement data storage.</p> <p>Note: All calibration data remains stored when this action is performed.</p>

Display presentation of a dataset



Sample

```
31.10.2008 09:56:20
pH 3310
Ser. no. 08502113

ID number 2
pH 6.012 24.8 °C, AR, +++
```

```
31.10.2008 10:56:20
pH 3310
Ser. no. 08502113

ID number 2
pH 6.012 24.8 °C, AR, +++
```

Quitting the display

To quit the display of stored measuring datasets, you have the following options:

- Switch directly to the measured value display with <M>.
- Quit the display and move to the next higher menu level with <F1>/[Back].

4.5.4 Erasing the measurement data storage

How to erase the measurement data storage is described in section 4.5.3 EDITING THE MEASURED VALUE STORAGE.

4.6 Transmitting data (USB interface)

4.6.1 Options for data transmission

Via the USB interface you can transmit data to a PC. The following table shows which data are transmitted to the interface in which way:

Data	Control	Operation / description
Current measured values of all connected sensors	Manual	<ul style="list-style-type: none"> With <F2>/[USB output]. Simultaneously with every manual storage process (see section 4.5.1).
	Automatic, at intervals	<ul style="list-style-type: none"> With <F2__>/[USB output]. Then you can set the transmission interval. Simultaneously with every automatic storage process (see section 4.5.2).
Stored measured values	Manual	<ul style="list-style-type: none"> Displayed dataset with <F2__>/[USB output] after calling up from the storage. All datasets with the Output to USB function. For details, see section 4.5.3.
Calibration records	Manual	<ul style="list-style-type: none"> Calibration record with <F2__>/[USB output]. For details, see section 4.6.
	Automatic	<ul style="list-style-type: none"> At the end of a calibration procedure.

Note



The following rule applies: With the exception of the menus, shortly pressing the **<F2>/[USB output]** key generally outputs the display contents to the interface (displayed measured values, measurement datasets, calibration records).

4.6.2 Connecting a PC

Connect the pH 3310 to the PC via the USB interface.



Warning

The USB interface is not galvanically isolated.

When a grounded PC is connected, measurements cannot be performed in grounded media as incorrect values would result.

Installation of the USB driver on the PC

System requirements of the PC for installation of the USB driver:

- PC with Pentium processor or higher with at least one free USB connection and CD-ROM drive
- Windows 2000, XP, Vista.

1	Insert the supplied installation CD in the CD drive of your PC.
2	Install the USB driver on the PC. Follow the Windows installation instructions as necessary.
3	Connect the pH 3310 to the PC via the USB interface. The meter is listed as a virtual COM interface among the connections in the Windows instrument manager.

4.7 Reset

You can reset (initialize) all sensor settings and sensor-independent settings separately from each other.

4.7.1 Resetting the measurement settings



Note

The calibration data are reset to the default settings together with the measuring parameters. Recalibrate after performing a reset.

- pH** The following settings for pH measurements are reset to the default settings with the *Reset* function:

Setting	Default settings
<i>Buffer</i>	TEC
<i>Cal. interval</i>	7 d
<i>Unit for slope</i>	mV/pH
Measured parameter	pH
Resolution pH	0.001
Resolution mV	0.1
Asymmetry	0 mV
Slope	-59.16 mV
<i>Man. temperature</i>	25 °C
<i>One point calibration</i>	Off

The sensor settings are reset under the *Reset* menu item in the measuring menu. To open the settings, activate the relevant measuring window in the measured value display and press the **<F1>/[Menu]** key shortly.

4.7.2 Resetting the system settings

The following system settings can be reset to the delivery status:

Setting	Default settings
<i>Language</i>	English
<i>Temperature unit</i>	°C
<i>Beep</i>	On
<i>Baud rate</i>	4800 Baud
<i>Output format</i>	ASCII
<i>Contrast</i>	50 %
<i>Illumination</i>	On
<i>Switchoff time</i>	1 h

The system settings are reset in the menu, *Storage & config / System / Reset*. To open the *Storage & config* menu, press the **<F1 __>/[Menu]** key in the measured value display.

5 Maintenance, cleaning, disposal

5.1 Maintenance

The only maintenance activity required is replacing the batteries.




Note

See the relevant operating manuals of the combination electrodes for instructions on maintenance.

5.1.1 Replacing the batteries

- | | |
|---|---|
| 1 | Unscrew the two screws (1) on the underside of the meter. |
| 2 | Open the battery compartment (2) on the underside of the meter. |



- | | |
|---|---|
| 3 | Remove the four batteries from the battery compartment. |
| 4 | Place four new batteries (type Mignon AA) in the battery compartment. |



Note

Alternatively, you can also use Ni-MH rechargeable batteries (type Mignon AA). In order to charge the batteries, an external charging device is required.



Caution

Make sure that the poles of the batteries are positioned correctly. The ± signs on the batteries must correspond to the ± signs in the battery compartment.

- 5 | Close the battery compartment (2) and tighten the screws (1).

5.2 Cleaning

Occasionally wipe the outside of the meter with a damp, lint-free cloth. Disinfect the housing with isopropanol as required.

Caution

The housing is made of synthetic material (ABS). Thus, avoid contact with acetone or similar detergents that contain solvents. Remove any splashes immediately.



5.3 Packing

This meter is sent out in a protective transport packing. We recommend: Keep the packing material. The original packing protects the meter against damage during transport.

5.4 Disposal



Note

This meter contains batteries. Batteries that have been removed must only be disposed of at a recycling facility set up for this purpose or via the retail outlet.

It is illegal to dispose of it in household refuse.

6 What to do if...

Error message <i>OFL, UFL</i>	Cause	Remedy
pH combination electrode:		
– Measured value outside the measuring range	– Use suitable combination electrode	
– Air bubble in front of the junction	– Remove air bubble	
– Air in the junction	– Extract air or moisten junction	
– Cable broken	– Replace combination electrode	
– Gel electrolyte dried out	– Replace combination electrode	
Error message <i>Error</i>	Cause	Remedy
pH combination electrode:		
– The values determined for zero point and slope of the combination electrode are outside the allowed limits.	– Recalibrate	
– Junction contaminated	– Clean junction	
– Combination electrode broken	– Replace combination electrode	
Buffer solutions:		
– Incorrect buffer solutions	– Change calibration procedure	
– Buffer solutions too old	– Use only once. Note the shelf life	
– Buffer solutions depleted	– Change solutions	

No stable measured value

Cause	Remedy
pH combination electrode:	
– Junction contaminated	– Clean junction
– Membrane contaminated	– Clean membrane
Test sample:	
– pH value not stable	– Measure with air excluded if necessary
– Temperature not stable	– Adjust temperature if necessary
Combination electrode + test sample:	
– Conductivity too low	– Use suitable combination electrode
– Temperature too high	– Use suitable combination electrode
– Organic liquids	– Use suitable combination electrode

Sensor symbol flashes

Cause	Remedy
– Calibration interval expired	– Recalibrate the measuring system

Display

Cause	Remedy
– batteries almost empty	– Replace the batteries (see section 5.1 MAINTENANCE)

Obviously incorrect measured values	Cause	Remedy
	pH combination electrode:	
	<ul style="list-style-type: none"> – pH combination electrode unsuitable 	<ul style="list-style-type: none"> – Use suitable combination electrode
	<ul style="list-style-type: none"> – Temperature difference between buffer and test sample too high 	<ul style="list-style-type: none"> – Adjust temperature of buffer or sample solutions
	<ul style="list-style-type: none"> – Measurement procedure not suitable 	<ul style="list-style-type: none"> – Follow special procedure
Meter does not react to keystroke	Cause	Remedy
	<ul style="list-style-type: none"> – Operating condition undefined or EMC load unallowed 	<ul style="list-style-type: none"> – Processor reset: Press the <ENTER> and <On/Off> key simultaneously
You want to know which software version is in the meter	Cause	Remedy
	<ul style="list-style-type: none"> – E. g., a question by the service department 	<ul style="list-style-type: none"> – Switch on the meter. Open the menu, <F1__>[Menu] / Storage & config / System / Service information. The instrument data is displayed.

7 Technical data

7.1 General data

Dimensions	approx. 180 x 80 x 55 mm	
Weight	approx. 0.4 kg	
Mechanical structure	Type of protection	IP 67
Electrical safety	Protective class	III
Test certificates	CE, cETLus	
Ambient conditions	Storage	- 25 °C ... + 65 °C
	Operation	-10 °C ... + 55 °C
	Allowable relative humidity	Annual mean: < 75 % 30 days/year: 95 % Other days: 85 %
Power supply	Batteries	4 x 1.5 V alkali-manganese batteries, type AA
	Rechargeable batteries	4 x 1.2 V NiMH rechargeable batteries, type AA (no charging function)
	Operational life	up to 1000 h without / 150 h with illumination
Sensor input	Input resistance	> 5 * 10 ¹² ohm
	Input current	< 1 * 10 ⁻¹² A
USB interface	Type	USB 1.1 USB B (device), data output
	Baud rate	adjustable: 1200, 2400, 4800, 9600, 19200 Baud
	Data bits	8
	Stop bits	2
	Parity	None
	Handshake	RTS/CTS
	Cable length	max. 3 m
Guidelines and norms used	EMC	EC directive 2004/108/EC EN 61326-1 EN 61000-3-2 EN 61000-3-3 FCC Class A
	Meter safety	EC directive 2006/95/EC EN 61010-1
	IP protection class	EN 60529

7.2 Measuring ranges, resolution, accuracy

Measuring ranges, resolution

Variable	Measuring range	Resolution
pH	- 2.0 ... + 20.0	0.1
	- 2.00 ... + 20.00	0.01
	- 2.000 ... + 19.999	0.001
U [mV]	- 1200.0 ... + 1200.0	0.1
	- 2500 ... + 2500	1
T [°C]	- 5.0 ... + 105.0	0.1
T [°F]	23.0 ... + 221.0	0.1

Manual temperature input

Variable	Range	Increment
T _{manual} [°C]	- 25 ... + 130	1
T _{manual} [°F]	-13 ... + 266	1

Accuracy (± 1 digit)

Variable	Accuracy	Temperature of the test sample
<i>pH / range *</i>		
- 2.0 ... + 20.0	± 0.1	+ 15 °C ... + 35 °C
- 2.00 ... + 20.00	± 0.01	+ 15 °C ... + 35 °C
- 2.000 ... + 19.999	± 0.005	+ 15 °C ... + 35 °C

U [mV] / range

- 2500 ... + 2500	± 1	+ 15 °C ... + 35 °C
- 1200.0 ... + 1200.0	± 0.3	+ 15 °C ... + 35 °C

T [°C] / temperature sensor

NTC 30	± 0.1	
PT 1000	± 0.1	

* when measuring in a range of ± 2 pH around a calibration point

Note

The accuracy values specified here apply exclusively to the meter. The accuracy of the combination electrodes and buffer solutions has to be taken into account additionally.



FCC Class A Equipment Statement

Note: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications.

Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at his own expense.

Changes or modifications not expressly approved by the manufacturer could void the user's authority to operate the equipment.

8 Lists

This chapter provides additional information and orientation aids.

Specialist terms	The glossary briefly explains the meaning of the specialist terms. However, terms that should already be familiar to the target group are not described here.
Index	The index will help you to find the topics that you are looking for.
Glossary	
Adjusting	To manipulate a measuring system so that the relevant value (e. g. the displayed value) differs as little as possible from the correct value or a value that is regarded as correct, or that the difference remains within the tolerance.
Asymmetry	see zero point
AutoRange	Name of the automatic selection of the measuring range.
Calibration	Comparing the value from a measuring system (e. g. the displayed value) to the correct value or a value that is regarded as correct. Often, this expression is also used when the measuring system is adjusted at the same time (see adjusting).
Electromotive force of a combination electrode	The electromotive force U of the combination electrode is the measurable electromotive force of a combination electrode in a solution. It equals the sum of all the galvanic voltages of the combination electrode. Its dependency on the pH results in the electrode function, which is characterized by the parameters, slope and zero point.
Junction	The junction is a porous body in the housing wall of reference electrodes or electrolyte bridges. It arranges the electrical contact between two solutions and makes the electrolyte exchange more difficult. The expression, junction, is also used for ground or junction-less transitions.
Measured parameter	The measured parameter is the physical dimension determined by measuring, e. g. pH, conductivity or D.O. concentration.
Measured value	The measured value is the special value of a measured parameter to be determined. It is given as a combination of the numerical value and unit (e. g. 3 m; 0.5 s; 5.2 A; 373.15 K).

Molality	Molality is the quantity (in Mol) of a dissolved substance in 1000 g solvent.
ORP voltage	The ORP is caused by oxidizing or reducing substances dissolved in water, if these substances become effective at an electrode surface (e. g. a gold or platinum surface).
pH value	The pH is a measure of the acidic or basic effect of an aqueous solution. It corresponds to the negative decadic logarithm of the molal hydrogen ions activity divided by the unit of the molality. The practical pH value is the value of a pH measurement.
Potentiometry	Name of a measuring technique. The signal (depending on the measured parameter) of the electrode is the electrical potential. The electrical current remains constant.
Reset	Restoring the original condition of all settings of a measuring system.
Resolution	Smallest difference between two measured values that can be displayed by a meter.
Slope	The slope of a linear calibration function.
Stability control (AutoRead)	Function to control the measured value stability.
Standard solution	The standard solution is a solution where the measured value is known by definition. It is used to calibrate a measuring system.
Test sample	Designation of the test sample ready to be measured. Normally, a test sample is made by processing the original sample. The test sample and original sample are identical if the test sample was not processed.
Zero point	The zero point of a pH combination electrode is the pH value at which the electromotive force of the pH combination electrode at a specified temperature is zero. Normally, this is at 25 °C.

Index**A**

- Authorized use 10
Automatic switch-off 15
AutoRead
 pH 28, 30

B

- Battery compartment 13, 61

C

- Calibration
 pH 34
Calibration evaluation
 pH 37
Calibration interval 38
Calibration points
 pH 36
calibration records 46
Connecting a PC 57

D

- Dataset 49
Date and time 22
Default settings
 Measured parameter 58
 System settings 59
Display 7

E

- Energy saving feature 14
Energy saving mode 52

F

- Firmware update 75

I

- Initial commissioning 13, 14
Initialize 58
Interval
 calibration 38

K

- Keys 6

M

- Measured value display 17

Measurement accuracy 38

- Measurement data memory
 Edit 53
 Erase 53
 Storage locations 49
Measurement dataset 49
Measuring
 ORP 30
 pH 28

Measuring menu

- pH/ORP 32
Menus (navigation) 17
Messages 18

O

- Operational safety 10

P

- pH buffer sets 34
Precautions 9
Print 56

R

- Reset 58

S

- Safety 9
Saving 49
 At intervals 51
 Automatic 51
 Manual 50
Scope of delivery 13
Setting the date 14
Setting the time 14
Single-point calibration
 pH 41, 44
Slope
 pH 34
Socket field 8
Stability control
 Automatic 26
Storage interval 51

T

- Temperature measurement
 pH 27
Three-point calibration

pH 42, 45
Transmitting data 56
Transmitting measured values 56
Two-point calibration
 pH 41, 45

Z

Zero point of pH combination electrode .. 34

Appendix: Firmware update

General information

Available firmware updates are provided on the Internet. With the "Firmware Update" program and a PC you can update the firmware of the pH 3310 to the newest version.

For the update you have to connect the meter to a PC.

For the update via the USB interface, the following is required:

- a free USB interface (virtual COM port) on the PC
- the driver for the USB interface (on the enclosed CD-ROM)
- the USB cable (included in the scope of delivery of the pH 3310).

Program installation

1	Install the downloaded firmware update on a PC. An update folder is created in the Windows start menu. If an update folder already exists for the meter (or meter type), the new data is displayed there.
---	---

Program start

2	In the windows start menu, open the update folder and start the firmware update program.
---	--

Firmware update

3	Using the USB interface cable, connect the pH 3310 to a USB interface (virtual COM port) of the PC.
4	Switch on the pH 3310.
5	In the firmware update program, start the update process with OK.
6	Follow the instructions of the firmware update program. During the programming process, a corresponding message and a progress bar (in %) are displayed. The programming process takes approx. three minutes. A terminatory message is displayed after a successful programming process. The firmware update is completed.
7	Disconnect the pH 3310 from the PC. The pH 3310 is ready for operation again.

After switching the meter off and on you can check whether the meter has taken over the new software version (see page 65).



Wissenschaftlich-Technische Werkstätten GmbH

Dr.-Karl-Slevogt-Straße 1
D-82362 Weilheim

Germany

Tel: +49 (0) 881 183-0
+49 (0) 881 183-100
Fax: +49 (0) 881 183-420
E-Mail: Info@WTW.com
Internet: <http://www.WTW.com>